RUST PREVENTION MAGIC



RPM Treated Metal

Untreated Bare Metal

KEEPS METAL PARTS LOOKING BRAND NEW!

PROTECTS AGAINST

- RUST OILS
- SALT
 OXIDATION
 - ACIDS CORROSIVES

1-855-532-7846

www.MagicGuard.com





Heat Part

Metal surface should be free Surface should be warm enough for RPM of any rust or oxidation to liquify upon contact (150°-160°)



Brush RPM onto Part

The are address to have



Dab a small amount of RPM on the supplied brush and apply it to the warmed surface



Application Complete!

Allow part to cool back to room temperature



