

C-9023-50A

Mount Position
Diagram



Mount kit contents:

- 2 thick mounts
- 2 thin mounts
- 2 small mounts
- 2 small dowels
- 4 large dowels

Removal:

Spray all nuts to be removed generously with your favorite rust buster.

NOTE: When disassembling, note the quantity and positions of any parts that may have been inserted for body alignment. These parts will have to be reused if mount is on body alignment.

Remember: Do not use tools high enough to stretch & separate flanges. Always watch the air stream for sufficient clearance when raising the body. When jacking the body, use a long enough 2x4 or 4x4 for maximum support. Never put jack directly on body panels.

Final mounts one side at a time with both on other side secured only.

Return to factory specs.

