

*1967 and 1968 quarter panels were different in that the C-scoop contours changed. While the contour and depth at the door jamb was the same, the slope from the character line to the jamb was radically different. On the '67 the indentation drops steeply for about 5/8" and with a sharp bend slopes forward to the jamb. On the '68 the indentation slopes gently forward for about 2 1/2" then a soft radius slopes forward to the jamb.*

